

Eastwood Road Culvert Replacement

Existing 48" culvert pipe inlet, facing west (downstream)
Debris present from recent storm that overtopped road.



Photo: July 19th, 2017

Facing east (upstream) from existing 48" culvert pipe inlet



Photo: July 19th, 2017

Existing 48" culvert pipe outlet, facing west (downstream)



Photo: July 19th, 2017

Existing 48" culvert pipe outlet and plunge pool, facing east (upstream)




Photo: July 19th, 2017